

2018 ANNUAL INSPECTION REPORT FOR:

BLACK CREEK BOVINA DISTRICT

CENTER/GRAND CHUTE DISTRICT

CENTER VALLEY DISTRICT

DUCK CREEK DISTRICT

FREEDOM DISTRICT

NORTH LIBERTY DISTRICT

ONEIDA/HOBART DISTRICT

VANDENBROEK DISTRICT

PREPARED FOR:

OUTAGAMIE COUNTY DRAINAGE BOARD

PREPARED BY:

OUTAGAMIE COUNTY LAND CONSERVATION DEPARTMENT

3365 W. BREWSTER ST.

APPLETON, WI 54914

DATE: August 7th, 2018

The following pages report the information collected during the 2018 annual inspection of the 8 drainage districts located within Outagamie County. The annual inspections were conducted in the months of June and July by Greg Baneck, Land Conservation Department and various drainage board members.

The larger drainage districts were split into multiple maps for clarity. The index follows this page.

The report contains the following information that has been sorted alphabetically by drainage district:

1. SUMMARY OF LINEAR FEATURES NEEDING MAINTENANCE

For each District:

2. MAP OF LINEAR FEATURES NEEDING MAINTENANCE
3. MAPS OF POINT FEATURES NEEDING MAINTENANCE
4. MAPS OF LEGAL DRAINS NOT BUFFERED

The electronic data for the 2018 Annual Inspection can be found at:

s:\LC\DrainagBoard\AnnualInspections\2018

2018 ANNUAL INSPECTION REPORT FOR OUTAGAMIE
COUNTY DRAINAGE DISTRICTS

2018 Maintenance Linear Features

NAME	MAINTENANCE TYPE	LENGTH (FT)	NOTES
Black Creek/Bovina			
RemoveTrees			
		1,328	
		1,328	
		3,585	
	Sum =	6,241	
SprayBrush			
		14,946	
		3,456	
		2,485	
		458	
		14,946	
	Sum =	36,289	
Center Valley			
SprayBrush			
		2,653	
		751	
		897	
		2,829	
	Sum =	7,130	
Center/Grand Chute Central			
RemoveTrees			
		410	
		326	
		433	
		54	
	Sum =	1,223	
SprayBrush			
		1,279	
		562	
		872	
	Sum =	2,713	
Center/Grand Chute East			
Dredge			
		8,146	

NAME	MAINTENANCE TYPE	LENGTH (FT)	NOTES
		Sum = 8,146	
	SprayBrush		
		501	
		1,069	
		702	
		513	
		180	
		670	
		872	
		360	
		Sum = 4,867	
Center/Grand Chute West			
	Dredge		
		360	
		514	
		Sum = 874	
	RemoveTrees		
		326	
		921	
		Sum = 1,247	
	SprayBrush		
		211	
		398	
		Sum = 608	
Duck Creek Northeast			
	RemoveTrees		
		2,579	
		Sum = 2,579	
	SprayBrush		
		1,535	
		1,433	
		1,047	
		2,009	
		167	
		4,648	
		Sum = 10,840	

NAME	MAINTENANCE TYPE	LENGTH (FT)	NOTES
------	------------------	-------------	-------

**Duck Creek
Northwest**

Dredge

	959
Sum =	959

RemoveTrees

	665
	322
	584
Sum =	1,571

SprayBrush

	207
	2,374
	2,530
	1,810
	2,015
	4,648
	366
	2,346
	4,634
	780
	391
	1,203
	1,185
	2,074
Sum =	26,564

**Duck Creek
Southeast**

Dredge

	1,698
	739
Sum =	2,437

RemoveTrees

	1,262
	702
	158
	2,579
Sum =	4,701

SprayBrush

NAME	MAINTENANCE TYPE	LENGTH (FT)	NOTES
		3,358	
		405	
		1,995	
		1,416	
		406	
		588	
		782	
		553	
		Sum = 9,503	

SprayCattails

		562	
		Sum = 562	

Duck Creek Southwest

Dredge

		959	
		Sum = 959	

SprayBrush

		3,358	
		1,023	
		421	
		660	
		2,374	
		641	
		546	
		550	
		2,047	
		1,099	
		Sum = 12,720	

SprayCattails

		755	
		Sum = 755	

Freedom North

SprayBrush

		1,124	
		573	
		Sum = 1,697	

SprayCattails

NAME	MAINTENANCE TYPE	LENGTH (FT)	NOTES
		555	
		782	
		Sum = 1,337	

Freedom South

Dredge			
		822	
		Sum = 822	

Other			
		326	Watch for buffer vegetation sprayed
		117	Rock shoreline
		677	Reseed siseslope
		Sum = 1,120	

RemoveTrees			
		295	
		Sum = 295	

SprayBrush			
		1,921	
		2,577	
		660	
		176	
		709	
		136	
		825	
		1,553	
		364	
		311	
		1,921	
		985	
		Sum = 12,138	

SprayCattails			
		719	
		Sum = 719	

North Liberty

RemoveTrees			
		1,630	
		1,630	
		356	

NAME	MAINTENANCE TYPE	LENGTH (FT)	NOTES
		Sum = 3,616	
	SprayBrush		
		3,894	
		4,734	
		1,283	
		2,163	
		764	
		3,894	
		953	
		1,642	
		4,734	
		2,119	
		2,742	
		1,283	
		934	
		Sum = 31,139	
	SprayCattails		
		631	
		Sum = 631	
Oneida/Hobart Brown County			
	SprayBrush		
		2,350	
		2,350	
		Sum = 4,699	
Oneida/Hobart North			
	SprayBrush		
		1,723	
		1,220	
		1,234	
		592	
		2,023	
		402	
		1,857	
		1,917	
		300	
		Sum = 11,268	
	SprayCattails		
		384	

NAME	MAINTENANCE TYPE	LENGTH (FT)	NOTES
		367	
		Sum = 751	
Oneida/Hobart South			
	Dredge		
		1,465	
		2,294	
		Sum = 3,758	
	SprayBrush		
		1,107	
		415	
		Sum = 1,521	
	SprayCattails		
		252	
		1,510	
		Sum = 1,762	
Vandenbroek			
	Dredge		
		2,388	
		767	
		1,662	
		Sum = 4,817	
	RemoveTrees		
		248	
		67	
		Sum = 315	
	SprayBrush		
		444	
		944	
		646	
		742	
		3,260	
		785	
		529	
		Sum = 7,350	
	SprayCattails		
		545	
		568	

NAME	MAINTENANCE TYPE	LENGTH (FT)	NOTES
------	------------------	-------------	-------

Sum = 1,113

Sum SHAPE_Leng 234358.
170537