

**Black Creek/Bovina
Drainage District
2018 INSPECTION MAP**

Legend

× Maint_Point

Maintenance Needed

— Dredge

— Other


— RemoveTrees

— SprayBrush

— SprayCattails

— Maint_Line

- - - Legal Drain



2018 ANNUAL INSPECTION MAP
DISTRICT:



Notes:
Leave key for gate



PHOTO 1

DDP ID = 10472





PHOTO 2

2018 ANNUAL INSPECTION MAP
DISTRICT: Black Creek/Bovina



Notes:
Crossing needed



PHOTO 1

DDP ID = 10872




PHOTO 2

2018 ANNUAL INSPECTION MAP
DISTRICT: Black Creek/Bovina



Notes:
Clear brush



PHOTO 1

DDP ID = 10873




PHOTO 2