

North Liberty Drainage District

2018 INSPECTION MAP

Legend

× Maint_Point

Maintenance Needed

— Dredge

— Other


— RemoveTrees

— SprayBrush

— SprayCattails

— Maint_Line

- - - Legal Drain



2018 ANNUAL INSPECTION MAP DISTRICT: North Liberty



PHOTO 1

DDP ID = 10072




PHOTO 2

2018 ANNUAL INSPECTION MAP
DISTRICT: North Liberty



PHOTO 1

DDP ID = 10073




PHOTO 2