

**Oneida/Hobart Brown County  
Drainage District**

**2018 INSPECTION MAP**

**Legend**

- × Maint\_Point
- Maintenance Needed**
- Dredge
- Other
- RemoveTrees
- SprayBrush
- SprayCattails
- Maint\_Line
- - - Legal Drain

2018 ANNUAL INSPECTION MAP  
DISTRICT: Oneida/Hobart Brown County




PHOTO 1

DDP ID = 4871






PHOTO 2





### Oneida/Hobart North Drainage District

### 2018 INSPECTION MAP

**Legend**

- × Maint\_Point
- Maintenance Needed**
- Dredge
- Other
- RemoveTrees
- SprayBrush
- SprayCattails
- Maint\_Line
- - - Legal Drain

2018 ANNUAL INSPECTION MAP  
DISTRICT: Oneida/Hobart North




PHOTO 1

DDP ID = 4870






PHOTO 2




**Oneida/Hobart South  
Drainage District  
2018 INSPECTION MAP**

**Legend**

- × Maint\_Point
- Maintenance Needed**
- Dredge
- Other
- RemoveTrees
- SprayBrush
- SprayCattails
- Maint\_Line
- - - Legal Drain





**Legend**

**Buffer Inspection 2018**

**Buffer\_Type**

- Documenting Other situations
- No Buffer Left side looking downstream
- No Buffer Right side looking downstream
- No Buffer both sides
- - - Legal Drain
- bufferparcels2017
- - - Buffer Inspection 2017
- Buffer Inspection 2016

**2018 BUFFER INSPECTION MAP**

VANDENENG, JAMES  
Parcel Number: 130001402

