

**2019 ANNUAL INSPECTION REPORT FOR:**

BLACK CREEK BOVINA DISTRICT

CENTER/GRAND CHUTE DISTRICT

CENTER VALLEY DISTRICT

DUCK CREEK DISTRICT

FREEDOM DISTRICT

NORTH LIBERTY DISTRICT

ONEIDA/HOBART DISTRICT

VANDENBROEK DISTRICT

**PREPARED FOR:**

OUTAGAMIE COUNTY DRAINAGE BOARD

**PREPARED BY:**

OUTAGAMIE COUNTY LAND CONSERVATION DEPARTMENT

3365 W. BREWSTER ST.

APPLETON, WI 54914

**DATE: September 17th, 2019**

The following pages report the information collected during the 2019 annual inspection of the 8 drainage districts located within Outagamie County. The annual inspections were conducted in the months of June and July by Greg Baneck, Land Conservation Department and various drainage board members.

The larger drainage districts were split into multiple maps for clarity. The index follows this page.

The report contains the following information that has been sorted alphabetically by drainage district:

1. SUMMARY OF LINEAR FEATURES NEEDING MAINTENANCE

For each District:

2. MAP OF LINEAR FEATURES NEEDING MAINTENANCE
3. MAPS OF POINT FEATURES NEEDING MAINTENANCE
4. MAPS OF LEGAL DRAINS NOT BUFFERED

The electronic data for the 2019 Annual Inspection can be found at:

S:\LC\DrainageBoard\AnnualInspections\2019

2019 ANNUAL INSPECTION REPORT FOR OUTAGAMIE  
COUNTY DRAINAGE DISTRICTS

# 2019 Maintenance Linear Features

---

**Black Creek/Bovina**

---

Maintenance Type	Length (ft)	Notes
Phragmites		
	95	
	<b>Sum:</b>	<b>95</b>

---

RemoveTrees		
	134	
	168	
	1728	
	<b>Sum:</b>	<b>2030</b>

---

SprayBrush		
	1036	
	996	
	98	
	639	
	868	
	1232	
	1657	
	42	
	1388	
	540	
	609	
	347	
	<b>Sum:</b>	<b>9453</b>

---

---

## Center Valley

---

Maintenance Type	Length (ft)	Notes
RemoveTrees	1913	Brush cutting
<b>Sum:</b>	<b>1913</b>	
<hr/>		
SprayCattails	391	Spray brush
<b>Sum:</b>	<b>391</b>	
<hr/>		

---

## Center/Grand Chute Central

---

Maintenance Type	Length (ft)	Notes
SprayBrush	221	
	387	
	337	
	276	
	544	
	693	
	<b>Sum:</b>	<b>2458</b>

---

---

## Center/Grand Chute East

---

Maintenance Type	Length (ft)	Notes
Phragmites		
	144	
	109	
	<b>Sum:</b>	<b>253</b>

---

SprayBrush		
	855	
	340	
	420	
	178	
	439	
	2977	
	1383	
	853	
	<b>Sum:</b>	<b>7444</b>

---

SprayCattails		
	519	
	413	
	<b>Sum:</b>	<b>933</b>

---



---

## Center/Grand Chute West

---

Maintenance Type	Length (ft)	Notes
Phragmites		
	177	
	51	
	<b>Sum:</b>	<b>227</b>

---

SprayBrush		
	158	
	284	
	365	
	267	
	<b>Sum:</b>	<b>1074</b>

---

SprayCattails		
	1147	
	626	
	22	
	344	
	<b>Sum:</b>	<b>2139</b>

---

---

## Duck Creek Northeast

---

Maintenance Type	Length (ft)	Notes
SprayBrush	371	
	989	
	642	
	233	
	968	
	<b>Sum:</b>	<b>3202</b>

---

SprayCattails	24	
	<b>Sum:</b>	<b>24</b>

---

---

## Duck Creek Northwest

---

Maintenance Type	Length (ft)	Notes
RemoveTrees	1337	
	<b>Sum: 1337</b>	

---

SprayBrush	120	
	239	
	162	
	389	
	299	
	261	
	185	
	<b>Sum: 1655</b>	

---

SprayCattails	49	
	934	
	156	
	577	
	621	
	376	
	434	
	397	
	336	
	489	
	80	
	<b>Sum: 4449</b>	

---

---

## Duck Creek Southeast

---

Maintenance Type	Length (ft)	Notes
Dredge	1426	
<b>Sum:</b>	<b>1426</b>	

---

Phragmites	145	
<b>Sum:</b>	<b>145</b>	

---

RemoveTrees	101	
<b>Sum:</b>	<b>101</b>	

---

SprayBrush	1296	
	492	
	557	
	121	
	478	
	400	
<b>Sum:</b>	<b>3344</b>	

---

SprayCattails	373	
	265	
<b>Sum:</b>	<b>638</b>	

---

---

## Duck Creek Southwest

---

Maintenance Type	Length (ft)	Notes
SprayBrush	38	
	464	
	399	
	575	
	119	
	147	
	105	
	<b>Sum:</b>	<b>1847</b>

---

---

## Freedom North

---

Maintenance Type	Length (ft)	Notes
------------------	-------------	-------

Phragmites

443

**Sum: 443**

---

SprayCattails

2007

655

**Sum: 2662**

---

---

## Freedom South

---

Maintenance Type	Length (ft)	Notes
Dredge		
	598	
	617	
	<b>Sum:</b>	<b>1215</b>

---

Other		
	143	Bank erosion
	<b>Sum:</b>	<b>143</b>

---

RemoveTrees		
	254	
	<b>Sum:</b>	<b>254</b>

---

SprayBrush		
	492	
	323	
	521	
	274	
	212	
	701	
	117	
	185	
	129	
	528	
	1277	
	176	
	1082	
	277	
	<b>Sum:</b>	<b>6295</b>

---

SprayCattails		
	303	
	897	

---

---

## Freedom South

---

Maintenance Type	Length (ft)	Notes
	1837	
	1524	
	188	
	<b>Sum:</b>	<b>4749</b>

---



---

**North Liberty**

---

Maintenance Type	Length (ft)	Notes
SprayBrush		
	540	
	98	
	319	
	1577	
	435	
	769	
	477	Spray cattails
	367	
	619	
	328	
	264	
	0	
	<b>Sum:</b>	<b>5794</b>

---

**SprayCattails**

	556	
	207	
	330	
	547	
	2126	
	<b>Sum:</b>	<b>3766</b>

---

---

## Oneida/Hobart Brown

---

Maintenance Type	Length (ft)	Notes
Phragmites	85	
<b>Sum:</b>	<b>85</b>	
SprayBrush	497	
	604	
<b>Sum:</b>	<b>1102</b>	
SprayCattails	313	
<b>Sum:</b>	<b>313</b>	

---

---

## Oneida/Hobart North

---

Maintenance Type	Length (ft)	Notes
Phragmites		
	511	
	207	
	<b>Sum:</b>	<b>718</b>

---

SprayBrush		
	489	
	1625	
	1131	
	775	
	53	
	676	
	683	
	618	
	541	
	<b>Sum:</b>	<b>6590</b>

---

SprayCattails		
	1736	
	1803	
	867	
	470	
	441	
	135	
	<b>Sum:</b>	<b>5452</b>

---

---

**Oneida/Hobart South**

---

Maintenance Type	Length (ft)	Notes
Phragmites	91	
<b>Sum:</b>	<b>91</b>	
SprayBrush	310	
<b>Sum:</b>	<b>310</b>	
SprayCattails	39	
<b>Sum:</b>	<b>39</b>	

---

---

## Vandenbroek

---

Maintenance Type	Length (ft)	Notes
Phragmites		
	293	
	77	
	390	
	<b>Sum:</b>	<b>760</b>

---

RemoveTrees		
	132	
	<b>Sum:</b>	<b>132</b>

---

SprayBrush		
	183	
	598	
	411	
	232	
	212	
	145	
	294	
	623	
	355	
	417	
	422	
	<b>Sum:</b>	<b>3894</b>

---

SprayCattails		
	763	
	150	
	386	
	243	
	196	
	659	
	115	
	275	
	377	
	1524	
	1105	

---

## Vandenbroek

---

Maintenance Type	Length (ft)	Notes
	100	
	<b>Sum:</b>	<b>5893</b>

---

---

---

## Report Totals

Count: 183

Date Exported: 8/12/2019 2:25 PM

---

Total Length Sum: 97276